



PRIME DESIGN

Architecture Interiors

CERTIFICATE

We have visited the site of Saraswati Vidyalaya Senior Secondary School for girls by Istri Shiksha Pracharni Sabha on June 30, 2023 for the purpose of inspecting the structural stability of the building.

During the course of my inspection, it was observed that the structure at present is in four blocks with mummy on top and part structure is three storey frame structure.

I have checked all structural parts, calculated their strength and accordingly, certify, that present structure is structurally safe and strong

My certification is based on permissible stresses and slenderness ratio, relevant standards of Bureau of Indian Standard (IS 1893, IS 4326, IS 456) as applicable for construction of the building for structural stability to withstand/resist vertical as well Earth Quake impact.



(NEERAJ GUPTA)